

## **HISTORIC AMERICAN BUILDINGS SURVEY**

### **INDEX TO PHOTOGRAPHS**

U.S. NAVAL BASE, PEARL HARBOR, MACHINE SHOP  
(U.S. Naval Base, Pearl Harbor, Naval Shipyard, Facility Nos. 67 &  
67B)  
Sixth Street opposite 10-10 Pier  
Pearl Harbor  
Honolulu County  
Hawaii

HABS HI-491

### **INDEX TO BLACK AND WHITE PHOTOGRAPHS**

David Franzen, photographer, 2001

HI-491-1	Contextual overview, showing an oblique view of the west end. View facing southeast
HI-491-2	Partial view of the west end. View facing east
HI-491-3	Oblique exterior view of the east end and the north side. View facing northwest
HI-491-4	View of east end, taken from Facility 155. View facing west
HI-491-5	Oblique view of the south side, taken from Facility 155. View facing northwest
HI-491-6	Partial view of the south side, taken from Facility 9. View facing northeast
HI-491-7	View of the north side. View facing southwest
HI-491-8	Partial view of the western end of the south side, showing Facility 67B on the left. View facing northeast
HI-491-9	Overview of the interior, from the stairs to the second floor of Facility 67B. View facing southeast
HI-491-10	Interior view of the south side bay, from the stairs to the second floor. View facing east

U.S. NAVAL BASE, PEARL HARBOR, MACHINE SHOP

HABS HI-491  
INDEX TO PHOTOGRAPHS  
PAGE 2

HI-491-11	Oblique view of the south side wall, showing the lathe for the drive shafts and the ramp to the lower section. View facing west
HI-491-12	Interior view of the center bay, looking down the ramp. View facing west
HI-491-13	Interior view of the south and center bays, from the center ramp. View facing west
HI-491-14	Oblique interior view of the north side bay. View facing north
HI-491-15	Partial view of the west end interior wall of Facility 67, showing the wood framing of Facility 67B. View facing west
HI-491-16	Detail of the crane ladder and the pivoting windows at the west end. View facing north
HI-491-17	View across the west end, toward Facility 67A. View facing north
HI-491-18	View of the north side column and crane supports. View facing northeast
HI-491-19	Detail of the clerestory. View facing northwest
HI-491-20	Interior of the supervisors' bathroom on the second floor.